## General Risk Assessment for Hirers

Business Name:	Risk Assessor:		Image:	
Minchinhampton	Name	Julie Thayer		
Market House	Job Title	Consultant – Envesca Ltd		
	Date	April 2023		
	Signed	NA		

## Location of Hazard / Area / Process / Equipment: All areas

Activities:	How Harm Could Occur:	People Who Could be Harmed:		
Use of the Market	<ul> <li>Slips and Trips causing</li> </ul>	Employees	$\square$	
House including	bruise/broken bones/cuts	Public / Customers	$\square$	
Stage, Main Room, Chair Lift and Undercroft	<ul> <li>Electrocution causing burns or fire</li> <li>Falls from height causing serious injuries</li> <li>Entanglement/entrapment in chair lift</li> <li>Fire from flammable substances, decorations or unauthorised heaters causing burns or smoke inhalation</li> </ul>	Contractors		

Current Risk Rating (before controls are in place)						
Low		Medium	$\boxtimes$	High		

## **Control Measures Required**

- Ensure that furniture does not block the fire exits and ensure that there is sufficient space left between furniture to allow for a corridor walkthrough
- All fire doors to be closed at all times
- Do not position furniture too close to hot surfaces such as radiators
- Ensure that waste and debris is removed
- Make sure that spillages are cleaned up as soon as they occur, use warning signs
- Operate a clean as you go policy
- Be aware of uneven flooring in the Undercroft
- Ensure there is always suitable lighting
- Ensure that maximum numbers are not exceeded 10 seated theatre style and 80 seated at tables
- Ensure all electrical equipment used is safe and in good working order
- Organiser to make sure all activities on the stage are controlled and supervised to prevent potential fall from the stage.
- Ensure there are not any highly flammable, items of combustible nature or heaters brought into the premises.
- Ensure that all appropriate persons receive training in operating the chair lift safely and are made aware of possible entanglement such as loose clothing, etc., to be secured
- Ensure leads/cables are positioned to avoid tripping hazard
- Ensure that all equipment is safely turned off before leaving

Residual risk factor after measures taken						
Low	$\boxtimes$	Medium		High		
Risk Assessment Owned / Managed by:						
Name						
Job Title						
Date						
Review date						