



Risk Assessment

Toilets

Business Name:		Risk Assessor:		Image:
Minchinhampton Market House	Name	Neil James		
	Job Title	Consultant – Envesca Ltd		
	Date	11 th October 2022		
	Signed			

Location of Hazard / Area / Process / Equipment:	Toilet Facilities
--	-------------------

Activities:	How Harm Could Occur:	People Who Could be Harmed:						
Provision of safe working toilet facilities.	<ul style="list-style-type: none"> • Water overflow from sinks/urinals/toilets - Biological • Lingering smells - Physical • Become unhygienic - Biological 	<table border="1"> <tr> <td>Employees</td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>Public / Customers</td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>Contractors</td> <td><input checked="" type="checkbox"/></td> </tr> </table>	Employees	<input checked="" type="checkbox"/>	Public / Customers	<input checked="" type="checkbox"/>	Contractors	<input checked="" type="checkbox"/>
Employees	<input checked="" type="checkbox"/>							
Public / Customers	<input checked="" type="checkbox"/>							
Contractors	<input checked="" type="checkbox"/>							

Current Risk Rating (before controls are in place)			
Low	<input type="checkbox"/>	Medium	<input type="checkbox"/>
		High	<input checked="" type="checkbox"/>

Control Measures
<ul style="list-style-type: none"> • Regularly inspected. • Regularly cleaned. • Electric hand dryers installed and maintained.

Residual risk factor after measures taken			
Low	<input checked="" type="checkbox"/>	Medium	<input type="checkbox"/>
		High	<input type="checkbox"/>

Risk Assessment Owned / Managed by:	
Name	
Job Title	
Date	
Review date	