Risk Assessment	Undercroft – Front of Building			
Business Name:	Risk Asse	ssor:	Image:	
Minchinhampton	Name	Neil James		
Market House	Job Title	Consultant – Envesca Ltd		
	Date	11 <sup>th</sup> October 2022		
	Signed	166		

Location of Hazard / Area / Process / Equipment: Under

Under croft – Front of Building.

Activities:	How Harm Could Occur:	People Who Could be Harmed:		
Use of Undercroft	<ul> <li>Potential fire hazard.</li> <li>Potential for hazardous waste i.e. drug needles etc.</li> <li>Outside ground entrance is uneven.</li> </ul>	Employees     Image: Contractors       Public / Customers     Image: Contractors		

Current Risk Rating (before controls are in place)						
Low		Medium		High	$\boxtimes$	

## **Control Measures**

- Area to be monitored regularly, and action is taken accordingly.
- Remove any rubbish left by the public on a regular basis.
- Consider signage outside the entrance to raise awareness of the uneven flooring.

Residual risk factor after measures taken					
Low		Medium		High	
Risk Assessment Owned / Managed by:					
Name					
Job Title					
Date					
Review date					